

Figure E.51 Time Step of Surface Corrosion for 3.0% Chloride Post-Cracked Specimens




Figure E.52 Time Step of Rib Loss for 3.0% Chloride Post-Cracked Specimens